

ANDREW M. CUOMO Governor

ROSE HARVEY
Commissioner

HAROLD B. JOHNSON II
Commission Chairman

PEYTON A. TAYLOR Regional Director

Closure Report for Class V Injection Well – Large Capacity Cesspool

Macomb Reservation State Park, 201 Campsite Road, Schuyler Falls, NY 12985 Comfort Station #8 (Injection Well #4)

(revised 3-29-16)

Background & Intent: It is the intent to close the existing cesspool/seepage pits adjacent to comfort station building #8 (Injection Well #4) (see attached Map). EPA/DEC is requiring us to close the cesspool/seepage pits for each facility listed above.

- A) Location plan and site plan of the closures: see attached.
- **B)** Description of Business: Camping/campsites/RV Park for the public. SIC code is 7033.
- C) <u>Description of Fluids injected:</u> Sanitary Human Waste There are no drains of any kind located near chemicals / or where Chemical wastes are stored delivered or generated.
- **D)** Connection between drains and Injection wells: The entire well and connection drain was removed.
- **E)** Description of cesspool closures: Site was excavated and backfilled with clean inert Sand and stone.
- **F)** Contaminant Removal: All waste/contaminated soils were removed from in and around the cesspool until visibly clean soil was reached. Removal was by excavation.
- **G)** Onsite storage: The material was in a tarp covered dump truck for no more than one day until disposal.
- H & I) Waste Characterization: Refer to section II which discusses Well Specific Sampling
 Requirements Section A. 1.) Large Capacity cesspools that have received only sanitary waste.
 Requirement as follows: "Large capacity" means serves or designed to serve 20 or more people per
 day. The cesspool must be pumped out and the wastes must be disposed of properly by a licensed
 hauler. Excavation, end-point sampling and analysis are typically not required." The waste/fluids
 that entered the Class V well previously were untreated sanitary waste containing human excreta.
 No testing was conducted.
- J) **Backfill:** The site was backfilled with clean inert Sand and Stone.
- K) Final Closure Report: Final Closure Report was sent to:

Nicole Kraft Chief Ground Water Compliance Section U.S. Environmental Protection Agency 290 Broadway, 20th Floor New York, NY 10007-1866

Pictures

